COMPLETION REPORT

1.	Name of Work	:	**MAINTENANCE OF BOREWELL AT SIDEDAHALLI VILLAGE LIMIT IN BAGALAGUNTE IN WARD NO.14.**
2.	Sanctioned Estimate No. & Dt	:	
3.	Head of Account which is Chargeable	:	P-Col 1771.
4.	Work Order No. & Dt	:	
5.	Name of Contractor	:	**SRI B M YOGANANDA**
6a.	Time stipulated for completion of work	:	
b.	Delay in execution of work	:	--
7.	Measurement recorded in	:	M.B. No. 1680/10-11
8.	Check measurement of the Asst.	:	M.B. No. 1680/10-11 Page No 1629721 to 1629722
	Asst. Exe. Eng. / Exe. Eng	:	Page No. 1629721 to 1629722
9.	Name of the Office / Official	:	
	incharge of the work	:	
10.	a) Asst. Engineer		ಡಿ.ಎಸ್.ದಾಸರಹಳ್ಳಿ
	b) Asst. Exe. Engineer		ಕಾರ್ಯಪಾಲಕ

Sanctioned estimated amount	Amount claims as per actually vide as per bills	DIFFERENCE	
		Excess	Savings
10 lacs	9,53,690/-	—	46310/-

1) Certified that the above work has been completed within the stipulated time noted in the work order.
2) Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3) Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

ASST. ENGINEER
W-14

EXECUTIVE ENGINEER
ACCOUNTS SUPTD. (
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Zone, Bangalore-57.

ASST. EXECUTIVE ENGINEER
SUB DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE